

10/038189

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,767,697 B2  
DATED : July 27, 2004  
INVENTOR(S) : Uchida et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title page.

Item [56], References Cited, OTHER PUBLICATIONS, "(Doc. ID: JP 062990496 A)  
\*" should read -- (Doc. ID: JP 06290496 A)\* --

Column 15.


Line 32, "from th substrate side," should read -- from the substrate side, --

Column 16.

Line 8, "whereby trucking servo" should read -- whereby tracking servo --

Signed and Sealed this

Fifth Day of April, 2005



JON W. DUDAS  
*Director of the United States Patent and Trademark Office*